# Oil Field Environmental Incident Summary

Responsible Party: Trustland Oilfield Services

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: MARY R SMITH 5-8HX

Field Name: VAN HOOK Well File #: 22109

Date Incident:3/23/2014Time Incident:12:00Facility ID Number:County:MOUNTRAILTwp:150Rng:92Sec:5Qtr:

Location Description:

Submitted By: Jim Raley Received By:

Contact Person: Matt Kelly

3891 87th Ave NW New Town, ND 58763

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 5 Barrels 5 Barrels 5 barrels

Brine Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 4/14/2014 Clean Up Concluded: 4/8/2014

**Risk Evaluation:**No risk assessed.

Areal Extent:

## Potential Environmental Impacts:

No water was impacted or threatened to be impacted. No equipment was damaged and no personal injury occurred as a result of this incident. Impacts are limited to soils on location.

#### Action Taken or Planned:

Vac truck was immediately dispatched to remove any free liquids. Environmental clean up crew was dispatched to remove any impacted soils and transport to disposal.

Wastes Disposal Location: At an approved facility- Prairie Disposal

Agencies Involved: MHA, BIA

#### **Updates**

Date: 3/30/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to tank overflow, remained on location according to the report. NDIC retains oversight. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.